

# Electronic Holiday Detection (Jeeping)

- Visual inspection must supplement jeeping
- Problems identified
  - Bent defective spring
  - Not identifying and repairing all “jeeps”
  - Passing over visible holiday without the jeep sounding
  - Based on experience, jeep voltage may need to be set as high as 3500v to detect coating defects