

Interpass Temperature

- The temperature at a location near the start position of the welding arc(s) recorded immediately before initiating consecutive pass or passes. (from Appendix A)
- Minimum Interpass Temperature – generally preheat temperature
- Maximum Interpass Temperature – highest temperature allowed to start welding.