


DCVG Dig on First Phase



Disbonded girth weld
coating – poor surface
preparation