

# High Mechanized Defect Rate

- Causes
- Pipe sizing issues
- Inexperienced welders
- Start up issues
- X-ray or AUT falling behind eliminates timely feed back. Feed back is a valuable tool to improve weld quality.