

Preheat

- Heating the weld joint before welding
- Temperature of the weld joint immediately before the arc is struck.
- Procedures state Contact Pyrometer, or Temperature Indicating Crayon
- Range of preheat values found in the welding procedure