

Must follow welding procedure

- Some items to check
 - Bevel configuration
 - Electrodes – rods – filler metals
 - Electrical parameters
 - Speed of travel
 - Weld dimensions