

Electrical Characteristics

- Values displayed on welding machines should be within the range of the WPS.
- Machine is not calibrated but usually close.
- If outside procedure use calibrated clamp-on.

