

Image Quality Indicators (Penetrameters)

- PHMSA (OPS) recognizes the 20th editions of API 1104. The 20th edition **only** allows the use of Wire Type Image Quality Indicators.

