

Radiographic Problems Identified continued

- No repair radiograph
- Radiographed wrong defect area (multiple repairs)—should be able to match up unrepaired areas of repair radiograph to original radiograph
- Numbering irregularities (Changed numbers with magic marker)
- Radiographing same weld twice or multiple times and changed weld identification numbers
- IQI issues – essential wire not visible
- Poor radiographic technique used on transition welds – especially if there is a large difference in thickness