

Good patch stick application - notice heated/discolored area around patch, this indicates that the pipe was heated before and during patch stick application

