

Preheat

- What should workman do if the weld joint is too cool? (add more heat) What do you do? (document occurrence)
- What does welder do if the weld joint is too hot? (allow joint to cool) If the welder does not wait, what do you do? (document occurrence)

