

Welding Procedures

The procedure states 20 – 40 cfh shielding gas flow rate. Does the photo show an acceptable value? (No)

